


URS20 / URS26 Photoelectric Position Sensors

Connect either White or Black to the I/O. Use White for Dark-On (Active ON) or Black for Light-On (Active OFF). Connect Brown to +5 to 24VDC, and connect Blue to I/O Common.

Wiring diagram



Output operation

	Color code	Output operation
Output 1	Black	Light-ON
Output 2	White	Dark-ON

For Further Information Contact

Heason Technologies Group Ltd

Tel: +44(0)1403 755800

Fax: +44(0)1403 755810

Email: sales@heason.com

Freephone 0800 374903 www.heason.com

Heason
Technologies Group